


# Robotica Antropomorfa

## Lezione 5

OS 2005

## Control of a single joint




RA 2005

## Actuators

- Various types:
  - AC, DC, etc.
  - DC
    - Brushless
    - With brushes
- We'll have a look at the DC with brushes, simple to control, widely used in robotics


RA 2005

## DC-brushless



Copyright © 1998  
by Minimotor SA

## DC with brushes




Copyright © 1998  
by Minimotor SA

## Modeling the DC motor

- High stall torque
- Speed-torque and torque-current relationships are linear


RA 2005

## In particular



RA 2005

## Electrical schema



$$E_g = \omega(t)K_E$$

RA 2005

## Meaning of components

- $R_a$  • Armature resistance (including brushes)
- $V_{arm}$  • Armature voltage
- $R_l$  • Losses due to magnetic field
- $E_g$  • Back EMF produced by the rotation of the armature in the field
- $L_a$  • Coil inductance

RA 2005

## We can write...

$$V_{arm} = R_a I_a + L_a \dot{I}_a + \omega(t)K_E$$


for  $R_l \ll R_a$

which is the case at the frequency of interest, and we also have...

$$\tau = K_T I_a$$


RA 2005

## On torque and current



RA 2005

## Thus for many coils...



RA 2005

## Back to motor modeling...

$$\tau = (J_M + J_L)\dot{\omega}(t) + B\omega(t) + \tau_f + \tau_{gr}$$

- $\tau$  • Torque generated
- $J_M$  • Inertia of the motor
- $J_L$  • Inertia of the load
- $\tau_f$  • Friction
- $\tau_{gr}$  • Gravity

RA 2005

## Furthermore...

$$V_{arm} = R_a I_a + L_a \dot{I}_a + \omega(t) K_E$$

$$\tau = K_T I_a$$

$$\tau = (J_M + J_L)\dot{\omega}(t) + B\omega(t) + \tau_f + \tau_{gr}$$

RA 2005

## By Laplace-transforming

$$V_{arm}(s) = R_a I_a(s) + L_a I_a(s)s + \omega(s) K_E \Rightarrow I_a(s) = \frac{V_{arm}(s) - \omega(s) K_E}{R_a + L_a s}$$

$$\tau = K_T I_a$$

$$K_T \frac{V_{arm}(s) - \omega(s) K_E}{R_a + L_a s} = (J_M + J_L)\omega(s)s + B\omega(s) + \tau_f + \tau_{gr}$$

RA 2005


## and finally

$$\frac{\omega(s)}{V_{arm}(s)} = \frac{K_T / L_a J_T}{s^2 + [(R_a J_T + L_a B) / L_a J_T]s + (K_T K_E + R_a B) / L_a J_T}$$

- Considering gravity and friction as additional inputs


RA 2005

## Block diagram



RA 2005

## Back one lesson



RA 2005

## Error and performance

$$\vartheta = \frac{\vartheta_d}{s} \quad M(s) = \frac{K_T}{(R_a + sL_a)(B + sJ_T) + K_E K_T}$$

closed loop (velocity)  $\vartheta(s) = \frac{1}{s} \omega(s)$

closed loop (position)  $\vartheta(s) = \frac{1}{s} \omega(s)$

$$\omega(s) = \frac{A}{1 + s\tau_a} M(s)$$

$$\omega(s) = \frac{A}{1 + s\tau_a} M(s) K_g$$

$$\vartheta(s) = \frac{1}{s} \omega(s)$$

$$\vartheta(s) = \frac{1}{s} \frac{\omega(s)}{1 + \frac{1}{s} \omega(s) K_p}$$

RA 2005

## finally

$$\lim_{s \rightarrow 0} sH(s) = \lim_{t \rightarrow \infty} h(t)$$

$$\Rightarrow \lim_{s \rightarrow 0} s \frac{\vartheta_d}{s} \vartheta(s) = \lim_{s \rightarrow 0} \frac{s \frac{1}{s} \vartheta_d \omega(s)}{1 + \frac{1}{s} \omega(s) K_p} = \frac{\vartheta_d}{K_p}$$

- For zero error  $K$  must be 1 or the control structure must be different

RA 2005

## Same line of reasoning

$$\vartheta_{final} = -\frac{T_L R_a}{AK_T K_p}$$


- Final value due to friction and gravity

$$\left| \frac{T_L R_a}{AK_T K_p} \right| \leq \vartheta_{max} \Rightarrow K_p \geq \frac{T_L R_a}{AK_T \vartheta_{max}}$$

$$K_{pmin} = \frac{T_L R_a}{AK_T \vartheta_{max}}$$

RA 2005

## PID controller



RA 2005

## PID controller

- We now know why we need the proportional
- We also know why we need the derivative
- Finally, we add the integral
  - Integrates the error, in practice needs to be limited

RA 2005

## Interpreting the PID

- Proportional: to go where required, linked to the steady-state error
- Derivative: damping
- Integral: to reduce the steady-state error


RA 2005

## About the amplifiers

- Linear amplifiers
  - H type
  - T type
- PWM (switching) amplifiers

RA 2005

## Let's consider the linear as a starting point




RA 2005

## H-type

- The motor doesn't have a reference to ground (floating)
- It's difficult to get feedback signals (e.g. to measure the current flowing through the motor)

RA 2005

## T-type



RA 2005

## On the T-type

- Bipolar DC supply
- Dead band (around zero)
- Need to avoid simultaneous conduction (short circuit)

RA 2005

## Things not shown

- Transistor protection (currents flowing back from the motor)
- Power dissipation and heat sink
  - Cooling
- Sudden stop due to obstacles
  - High currents → current limits and timeouts

RA 2005

to be continued...

RA 2005